



Demolition continues on Pure Food Fish Floor



Concrete delivery for Corner Market



Work on the Corner Market Roof




Trenching in tight quarters in Can Can



Trenching in the Corner Market



Carting away concrete debris from trenching in Corner Market



Lighting in Women's Public Restrooms-Sanitary Building



Moving the drill from Corner Market to The Crumpet Shop along Pike Street



Installing toilet partitions in the Women's Public Restrooms-Sanitary Market




Moving the drill into the Crumpet Shop on First Avenue



Checking the tile work with the architect outside the Women's Public Restroom-Sanitary Mkt.



Removing debris by crane from the roof of the Corner Market



Cleaning leftover debris from Pike Place Pedestrian Walk



Drilling in Sanitary Market



Demo in Copa Cabana, Triangle Building



Abatement in the Can Can




Lahma Brace Frame




Trenching in the Corner Market



Running Condenser pipes in the Sanitary Market Trench



Corner Market Trenching



Corner Market Trenching



Safety Meeting in the Sanitary Market Atrium



Prepping to Drill for Hombow Brace Frame

